

Thank you for purchasing our Foaming Bath Butter Starter Kit!



To make your own Foaming Bath Butter, simply scoop out half of the foaming bath butter base from your 1KG tray into a large or deep pan.

Heat up your base and stir thoroughly throughout the heating process, checking the base temperature every minute until 60°C.

Once your base reaches 60°C, turn off the heat, it is important not to overcook your base as the bath butter could harden once it sets.

Now add your chosen oils, fragrances and colourants, carefully. Keep stirring throughout this process to make sure you keep an even distribution of ingredients. We suggest up to 15ml of colourant and 15ml of fragrance oil.

Once you have added all your chosen ingredients, remember to watch the temperature, do not let the base fall below 50°C as it will make the pouring process difficult.

Once your base has reached 50°C it is now time to pour your bath butter! Carefully pour the mixture into the provided 500ml tubs and leave to set.

Congratulations! You have now made your own Foaming Bath Butter.

Now repeat the process with your remaining bath butter using different colours or scents.

Why not decorate your tubs with gift wrapping, ribbons or even diamantes?



Soapsupplier.co.uk



Facebook.com/SoapSupplier

info@Soapsupplier.co.uk
01709 584995